

# Changelog

## Table of Contents

|   |                         |   |
|---|-------------------------|---|
| 1 | Products affected ..... | 2 |
| 2 | New features .....      | 2 |
| 3 | Issues fixed .....      | 2 |
| 4 | Upgrade procedure ..... | 2 |

# 1 Products affected

| Commercial reference | Product   | FW version |
|----------------------|-----------|------------|
| LSS100100            | homeLYnk  | 2.0.0      |
| LSS100200            | spaceLYnk | 2.0.0      |

Table 1: Products affected

## 2 New features

- Pincode is now ignored if object mode is set to start/stop or stop/start.
- Modbus: JSON profiles with UTF-8 are allowed
- Modbus: JSON error is shown when profile cannot be parsed

## 3 Issues fixed

- Turkish translation
  - Names of the days in scheduler is not shorted.
  - Missing translation for Edit button
- Category filter does not work in scripting
  - Filter is deleted after few seconds
- Empty string is ignored in object custom values
- Custom values of feedback object are missing
- Update of an application breaks the App
- Incorrect custom icon when status object has different data type from main object
- Object log now works properly when log policy is set to **all** and bus sniffer is **disabled**
- Remote services: object list is not working if a time/day object is exported
- Alert messages with % character cause an error

## 4 Upgrade procedure

1. Click *Configurator -> System -> System -> Upgrade firmware*
2. Find firmware for your product
3. Click OK

**Note:** It is recommended to create backup of your actual project before upgrade!